KIRTON CONCRETE SERVICES LTD INDEPENDENT TESTING LABORATORY

MANOD HOUSE STATION DOAD, HIRALDSTOW, RDICC, DN20 OFR

MANOR HOUSE, STATION ROAD, HIBALDSTOW, BRIGG. DN20 9EB TEL: 01652 656931 EMAIL: KIRTONLAB@AOL.COM



1175

TEST RESULTS

Client :- TITAN CEMENT LTD. HULL

Report reference :- CUBES 81

Ship reference :- "11-20

Sample :- ORDINARY PORTLAND CEMENT

Sand :- FRENCH

Date received :- 10-Nov-20

Date of tests :- 10-Nov-20 to 08-Dec-20

All results are based on sample received from the client

AT 3 DAY	32.1	33.2	33.0	Average	33.0 Mpa	BSEN 12390-2:2009
AT 7 DAY	34.5	38.5	41.0	Average	38.0 Mpa	BSEN 12390-2:2009
AT 28 DAY	61.0	61.1	59.7	Average	60.6 Mpa	BSEN 12390-2:2009

SLUMP 75 mm

End of Report

NOTE:- The slump test was carried out on 10/11/2020 at "14.11 as per BSEN 12350-2:2009 by B. Beck A 10 Litre mixer was used for the mixing of the sample, sampling was carried out in accordance with BSEN12350-1: 2009 The slump cone was filled and the test was carried out 2 minutes +/- 30s from the end of mixing.

The mixing, sampling and slump test were carried out at Kirton Concrete Services Ltd's. laboratory. The slump was a true slump.

Signed...... Page 3 of 3 Date 8.12.20

J.M. Burton Quality Manager

S. Burton Technical Manager